

病房門框生鏽統計表 1141028

1	2	13B03	
2	11	13B 負壓 4	
3	13	13B 負壓 6	
4	14	12A08	

5	15	12B15		
6	18	11A02		
7	23	11A07		
8	24	11A08		
9	33	11A18 (1 側)		

10	41	11B05		
11	43	11B07		
12	53	10A02		
13	55	10A04		
14	57	10A06		

15	58	10A07		
16	59	10A08		
17	60	10A10		
18	62	10A14		
19	63	10A15		

20	68	10B01		
21	69	10B02		
22	70	10B03		
23	71	10B04		
24	72	10B05		

25	73	10B06		
26	74	10B07		
27	75	10B08		
28	76	10B09		
29	81	10B14		

30	82	10B15		
31	85	10B18 (1 側)		
32	88	9A03		
33	110	9B05		
34	112	9B07		

35	116	9B11	
36	117	9B12	
37	126	8A03	
38	132	8A09	
39	135	8A12	

40	136	8A13	
41	137	8A14	
42	139	8A16 (1 側)	
43	142	8A19	
44	143	8B01	

45	148	8B06		
46	150	8B08		
47	152	8B10		
48	156	8B14		
49	159	7A03		

50	164	7A11	
----	-----	------	--

備註：

各樓層病房廁所門框除鏽破損修補

徹底除鏽或直接使用鏽轉化劑/漆=>塑鋼土或玻璃纖維補土修補破損處=>依原有漆號補色
(應該是國麗 K-2584 灰垂紋)